

0.6.2 sub revision(11 Dec 2018):

---

Simple improvements that make the boards easier to solder:

- improved buttons footprints on the UI board
- improved footprint on the aluminium caps
- removed lots of 0 Ohm jumpers that are rarely used(UI and RF)
- polygon connect method for all alu caps on the UI board improved

Mechanical changes:

- none

Schematics changes:

- Codec Digital supply now routed to MCU regulator
- Codec Analog supply still from RF board 3V supply
- The SWO pin on the Nucleo debug connector is wired now