

LPF Torroid winding guide

27 turn – 13.75”

24 turn – 12.5”

21 turn – 11”

19 turn – 10”

14 turn – 7.5 “

12 turn – 6.5”

9 turn – 5.25”

8 turn – 4.5”

T6 – 6”

T2 T3 – 8”

RFC8 – 3 – 4 turns

T7 – 2 turn primary – 3 turn secondary